

LH71A

LH71A



Initial Setup Manual

INITIAL SETUP FLOW



Table of contents

Contents	Page
Preparations before making the initial settings (checking conditions of use)	2 to 3
How to set up Basic Settings STEP 1~3	4 to 6
How to set up Detailed Settings (continued from Basic Settings) STEP 4~5	7
Factory Default (All Clear)	9
Appendix 1: Front panel, Alarm indication	10
Appendix 2: Adapter connections (scales and gauges)	11 to 12

Preparations before making the initial setting (1/2)

By confirming the conditions of use in advance, the setting operation can be performed easily.
Let's start with the basic settings.

Basic Setting Items









Items	Indication <small>default</small>	Description	Setting
Type (function selection)  LH71A-3 only		The function of LH71A-3 (3 axes) can be selected according to the type of machine used. Only GENERAL (general-purpose machine) can be selected for LH71A-1 / 2 (1 axis, 2 axes).	GENERAL: General-purpose machine LATHE: Lathe function
Addition display  Can be selected when "Lathe" (lathe function) is selected		Selection of addition axis, addition conditions, etc. If you select LATHE (lathe function) in the type selection, this item will appear.	2: No addition, count value of the 2nd axis 3: No addition, count value on the 3rd axis 2 Add 3: Count value of 2nd axis + 3rd axis 2 Add -3: Count value of 2nd axis-3rd axis -2 Add 3: 3rd axis-2nd axis count value -2Add-3: -2nd axis -3rd axis count value
Destination country 		Please select the region to be used. (Displayable units)	Std: General Area mm, inch US: U.S.A. mm, inch JPN: Japan mm
Measuring unit resolution 		Set the resolution output from the measurement unit to be used for each axis. The resolutions that can be selected are length and angle. Expanded selections increase the number of options.	Length: 0.05 to 100μm *See Tables 1, 2 and 3 or Angle: 1 second to 1 degree *Angular resolution (1sec to 1 degree) when using a rotary scale

Table1: Length scale output resolution

Measuring Unit	Output resolution	connection cable	Adapter *
SR-1711 SR-1711R	0.5μm	HK-**C HK-**CR	SZ05-T01
SR801/ MSS-101 SR801R	0.5μm	HK-1**C HK-2**C	SZ05-T01
SR801/ MSS-101 SR801R	0.5μm	CE07-**C	SZ51-MS01 + SZ70-1
SR10 / SR30 / SR50 SR50-R	0.5μm	HK-4**C HK6-**CR	SZ05-T01
SR118	0.5μm	CE05-**C CH02-**	DZ51 + SZ70-1
SR108 SR107	0.5μm		SZ51-MS01 + SZ70-1
SR128	0.5μm	CH01-**C	SZ70-1
SR128 / SR127	0.5μm	CH01-LW**C	SZ51-MS01 + SZ70-1
SR138R(GB-ER)	0.5μm	CH04-03C	

Table 2: Digiruler output resolution

Measuring Unit	Output resolution	Adapter/ conversion cable	Adapter *
SL110 SL130	10μm	PL20B	SZ70-1
SL110 SL130	10μm	PL20C	
SJ300	1μm	CH33-**CPD/CED	
SJ700	5μm		SZ70-1
SJ700A	5μm		

Table3: Digital gage output resolution

Measuring Unit	Output resolution	Adapter/ conversion cable	Adapter *
DG	0.5μm		SZ05-T01
DG-B	0.5μm	DZ-51	SZ70-1
DL310B/330B	10μm	DZ-51	SZ70-1
DK series	0.1μm or 0.5μm	CE29-**	

* For adapter information, refer to Appendix 2 Adapter Connection in this Manual

Preparations before making the initial setting (2/2)

Check the usage conditions for Detailed Settings.

(Since the setting conditions can be changed later, use the default values to skip items for which the conditions have not been confirmed)

Detailed Setting Items

Items	Indication <small>default</small>	Description	Setting
Display resolution and polarity 		Sets the resolution to be displayed for each axis. A value lower than the input resolution cannot be set. Selects the value for each axis, including the polarity (+/-). * The initial value is the measurement unit resolution set in the basic settings.	Length: 0.05 to 100μm or Angle: 1 second to 1 degree
Display switching 	Upper axis Middle axis Lower axis 	Each display axis can be selected for the length measurement unit input axis.	Input axis: IN-1: 1st input axis IN-2: 2nd input axis IN-3: 3rd input axis IN - -: No display
Axis label 	Upper : X Middle : Y	Display axis label selection Can be used with LH71A-1 and LH71A-2.	Upper axis: "X" or "Z" Middle axis: "Y" or "Z"
Scaling 		Displayed by multiplying the measured value by the magnification	0.1 times to about 10 times
Compensation value 		Setting of linear compensation and segmented error compensation	Err OFF : off Lin Err : linear compensation ±600μm/m *Expanded selections ±1000μm/m SEG Err : segmented error compensation
Flicker control 		Flickering of the smallest displayed digit can be suppressed. Set the level of flicker suppression.	OFF: Function stop 1: Weak 2: Strong
Sleep 		The display turns off when there is no movement of the length measurement unit or key operation for a certain period of time while the power is on. It will return when the length measurement unit is moved or the Key operation is performed again.	OFF: Do not put to sleep 1: 1 minute later 5: 5 minutes later 10: 10 minutes later 30: 30 minutes later 60: 60 minutes later
Touch sensor radius 		Touch sensor radius information setting (The radius of TS-1 and TS-3 is 5mm)	Setting range: 1.0 to 20.0 (mm)

How to set up Basic Settings (1/3)

Step 1

Configure the basic settings.
Choose one of the following methods of operation.

NOTE:



If you change the basic settings,
Detailed Settings will be reset to the factory defaults.

When the power is turned on for the first time after shipment from the factory

Connect the AC adapter and turn the primary power "on".



When you want to change the basic settings

AC adapter is energized.


Turn on  key, the LED light changes from "blinking" to "off" and then press and hold  key for 3 seconds.

The following display appears

Connecting the AC Adapter



After about 2 seconds





LH71A (1 axis / 2 axes input)



LH71A (3 axes input)

Continued on next page

Pressing  key changes the basic setting mode in the order in which it is set.



TYPE:
Switching of functional specifications between general-purpose machine (GENERAL) and lathe machine (LATHE).

ADD (additional display):
Selection of the 2nd and 3rd axes of the length measurement unit input and setting of addition display (**NOTE**)

COUNTRY (destination country):
Please select your region

Signal resolution (measuring unit resolution):
Sets the output resolution of the scale to be connected. Supports the input of length and angle display units.

NOTE: When "Lathe" (lathe function) is selected on the LH71A-3 (3-axis input), be sure to connect a scale with high resolution to the length measuring unit input axis 2 to display the addition.




COUNTRY (Destination)


Symbol	Destination	Unit
STD 	General area	
US 	U.S.A.	
JPN 	Japan	

How to set up Basic Settings (2/3)

Step 2

Enter the settings confirmed in "Preparations before making initial settings (1/2)". Repeat steps (1), (2), and (3) to make the basic settings.

- (1) Use  key to change the basic setting item.
- (2) The setting selection can be switched with  key on the right side of the counter display.
- (3) To define the new value, press  key.











How to set up Basic Settings (3/3)

Step 3


Once you have completed the basic settings, exit this mode and move to the Detailed Setting mode.

How to Exit Basic Setting Mode

- ① Press  key or  key.
- ② The display changes to .
- ③ Pressing  key displays .
- ④ Press  key. The display will be .
- ⑤ Press  key. The display returns to normal.

This completes the basic settings.

Key to be used at the end of the basic setting mode (LH71A)




How to set up Detailed Settings (1/1) (continued from Basic Settings)

Step 4 Make the detailed settings.


*If you have already completed the basic settings and want to reconfigure only the advanced settings, you can do the same.

Basic Settings





Press the setup key in the normal count display state.

- Display resolution is set by pressing key on each axis.
- A value smaller than the input resolution cannot be selected.
- Polarity changes with key
- To display the diameter (double display), turn on on the display axis.



NOTE 1: Selection of a value smaller than the basic setting length measurement unit resolution is not displayed.


NOTE 2: The angle display can be selected when the angle resolution is selected in the basic settings.



Selection of each display axis and measurement unit input axis



Display example LH71A-3

11 - 1	Upper: input 1	Set by select axis key
11 - 2	Middle: input 2	
11 - 3	Lower: input 3	



The axis labels for the 1st and 2nd axes can be selected from "X", "Y", and "Z".


NOTE: Can be used with LH71A-1 and LH71A-2.



Scaling magnification input

default 1000000

0.100000 ≤ magnification ≤ 9999999



Selection of error compensation function

default Err OFF

No compensation Error compensation off

Linear compensation Linear Error

Segmented error compensation Segmentation Error

Liner Error

Linear compensation

Segmentation Error

Segmented error compensation

Input a correction value of ± 0.600 mm for a distance of 1 m. Input up to ± 1.000 mm when extended is selected.

00000 (default)

Enter with the number keys


Normal -06000 ~ 06000

Extended res. -10000 ~ 10000

For the operation method, refer to the instruction manual or the simple manual (Segmented error compensation).

Segmented error compensation function uses a scale with reference point to correct mechanical errors for each interval.

The range that can be corrected is the range of the counter display based on the reference point position. In order to use this function, it is necessary to measure the section error of the machine with a laser interferometer, length reference device, etc. in advance.



Step 5

When the Detailed Settings are complete, switch to the normal display.


Press  key.

This completes the initial settings.

Factory Default (All Clear)

To set the factory settings (all clear), perform the following operations.
Make preparation such as taking NOTES in advance for necessary items.
Also, do not perform any operation other than the explanation.

CAUTION: IF YOU DO THIS, ALL SETTINGS WILL BE THE FACTORY DEFAULT SETTINGS.



1. Hold down key and key at the same time to start the power supply.


Connect the AC adapter to the DC-IN input on the back of the counter and turn on the primary power supply.

⇒ The model name of the counter is displayed

LH71A

2. When you press key is displayed, followed by

3. Pressing key changes the display as shown below.



4. "ARC" and "RUN" LEDs will be lit.
5. Press key to confirm the number of input axis.

In case of LH71A-1, is displayed.
In case of LH71A-2, is displayed.
In case of LH71A-3, is displayed.


6. Turn off the primary power supply of the AC adapter.

How to check the software version:

Power ON → Display LH → Key → Version
Press any key to return to the LH display.

Appendix 1

Front panel



No.	Name	No.	Name	No.	Name
①	Axis label	⑦	REF key	⑬	RUN/NEXT key
②	ABS lamp, Φ lamp	⑧	ABS/INC key	⑭	EDIT key
③	Counter display	⑨	SETUP key	⑮	Standby key
④	RESET key	⑩	PROG key	⑯	Axis select key
⑤	P key	⑪	Canned cycle key	⑰	Numeric key
⑥	Datum point value setting key	⑫	Status lamp	⑱	Function key

Alarm indication

Display	Status	Display	Status
	Measurement unit not connected		Storage data error
	Speed over (NOTE)		Error in reference point detection
	Overflow		Program error
	Power failure		Program error


NOTE: When using an adapter connection (SZ**), no speed override indication is shown, but rather an error message.




Appendix 2-1

Adapter connection (Length scale)

Scale/ Head	Resolution	Adapter	Counter
SR128(GB-A)	0.5μm	SZ70-1	LG20
PL20B	10μm		LH70/71/71A/72
SJ700	5μm		LY71/72




Scale/ Head	Resolution	Adapter 1	Adapter 2	Counter
SR108(GB)	0.5μm	SZ51-MS01	SZ70-1	LG20
PL20A	10μm	SZ51-DR01		LH70/71/71A/72 LY71/72



Scale	Resolution	Adapter	Counter
SR-1711(GP), SR10A/741(GS), SR50A(GF,GF-R), SR30A(GM), SR801/801R(GL)	0.5μm	SZ05-T01	LG20 LH70/71/71A/72 LY71/72

* HA13A, 15A, 23A and 25A are used as head amps




Appendix 2-2


Adapter connection (Digital gauge)




Gauge	Resolution	Connection cable	Counter
DK- ^{**}	0.1μm or 0.5μm	CE29- ^{**} ^{**} : 003/01/03/05/10 (0.3 to 10m)	LG20 LH70/71/71A/72 LY71/72



Gauge	Resolution	Adapter 1	Adapter 2	Counter
DG-B	0.5μm	DZ51	SZ70-1	LG20 LH70/71/71A/72 LY71/72
DL310B/330B	10μm			



Gauge	Resolution	Adapter	Counter
DG	0.5μm	SZ05-T01	LG20 LH70/71/71A/72 LY71/72



Gauge	Resolution	Adapter	Counter
DE12BR/30BR	0.1μm	SZ70-1	LG20 LH70/71/71A/72 LY71/72

