


# LH71 Initial setup (Example)

## Display unit: LH71-1 (1 axis input)



leasuring unit	
J700A (1 axis)	
output resolution: 5µm	





#### Setting conditions

The detailed settings are the factory default settings.

	Setting items		Setting value (selection)	
	TYPE	7478	1 axis model is not displayed	
Danie.	ADD(Addition display)	Rdd	1 axis model is not displayed	
Basic settings	Destination	<u> </u>	default STD	H
	Measuring unit resolution	516 rES	5μm	U
	Display resolution* and polarity	d5P rE5	5µт	U
Detailed	Display switching	INPUT CHRNGE	default Input 1:	
Detailed settings	Axis label	LRbEL	default Display : X	
	Scaling	SERL ING	default 1 time (1.000000)	10
	Compensation value	Err 587	default No setting (OFF)	F
	Flicker control	FL IEYEr	default Strong (2)	Ш
	Sleep	SLEEP	default No setting (OFF)	E

<sup>\*</sup> The initial value is the measurement unit resolution set in the basic settings.







Finished



## Display unit: LH71-2 (2 axes input)



Measuring unit	
SJ700A (2 axes)	
Output resolution: 5µm	





#### Setting conditions

The detailed settings are the factory default settings.

	Setting items		Setting value (selection)	
	TYPE	7426	2 axes model is not displayed	
B	ADD(Addition display)	Rdd	2 axes model is not displayed	
Basic settings	Destination	E0UN7r9	default STD	88888888
	Measuring unit resolution	516 rES	5µm	5-0
	Display resolution* and polarity	d5P rE5	5μm	H5-0
Detailed	Display switching	INPUT CHRNGE	default Input 1:Upper display Input 2:Middle display	IN - I
settings	Axis label	LRbEL	default Upper: X, Middle: Y	
	Scaling	SERL ING	default 1 time (1.000000)	-1000000
	Compensation value	Err 587	default No setting (OFF)	Err OFF
	Flicker control	FL IEYEr	default Strong (2)	88888888
	Sleep	SLEEP	default No setting (OFF)	BBB OFF BB

<sup>\*</sup> The initial value is the measurement unit resolution set in the basic settings.







Finished



## Display unit: LH71-3 (3 axes input)



Measuring unit
SJ700A (3 axes)
Output resolution: 5µm



#### Setting conditions

The detailed settings are the factory default settings.

	Setting items		Setting value (selection)	
	TYPE	7486	GENERAL (General machine )	GENE-RL
Basic	ADD(Addition display)	Rdd	Not displayed when GENERAL is selected	
settings	Destination	E0UA7r9	default STD	8885888
	Measuring unit resolution	516 rES	5μm	5-0
	Display resolution* and polarity	d5P rE5	5μm	5-0
Detailed settings	Display switching	INPUT CHANGE	default Input 1: Upper display Input 2: Middle display Input 3: Lower display	
	Axis label	LRbEL	default Upper : X, Middle : Y, Lower : Z	
	Scaling	SERL ING	default 1 time (1.000000)	1000000
	Compensation value	Err 587	default No setting (OFF)	Err OFF
	Flicker control	FL ICYEr	default Strong (2)	8888888
	Sleep	SLEEP	default No setting (OFF)	BBB OFFBB

<sup>\*</sup> The initial value is the measurement unit resolution set in the basic settings.

### START

#### Set to basic setting mode

When the power is turned on for the first time after shipment from the factory


Connect the AC adapter and Turn on the primary power supply

(Not key)


When you want to change the basic settings

AC adapter is energized.

Turn on key,
the LED light changes
from "blinking" to "off" and then
Press and hold key
for 3 seconds.



The following display appears





1
When the display is 7975, press the key once
The display will be . (Destination selection mode)
Press key on the right side once.
The display will be

( If you want to change the destination, press

key.)

When you have made your selection, press to save your settings.




The display will be 5 10 r 55 . (Measurement unit resolution)

Press key to check the current measurement unit resolution.

If the resolution is not 5µm, press key to change it.

After checking the resolution, press key to save the settings.



Confirm that the resolution of input 1,2, and 3 is 5 µm (SJ700A scale).
\* 10 µm "10U" for Digiruler PL20C

3

Switch from basic settings to normal count mode.

Press key once and the display will change to Press key once and the display will change to Press .

Press key once to automatically switch to advanced settings mode.

The display will be 557 7 55 . Press key once.

Confirm that the display is \_\_\_\_\_\_ display.

(Press key to change the polarity)

When the selection is complete, press key to save the settings.

When you press key, the display becomes the normal display.

This completes the initial settings

Finished